



NEW FROM VAL-TEX



LUBRICATOR, SEPARATOR, REGULATOR, PACKAGE



The most common issue with the **QS-2000A** is damage to the Enerpac pump due to dirty or wet air. A re-kit and repair of this problem is \$300-\$400 not including the cost of downtime, freight, and aggravation. Part number 2010 Regulator, Separator and Lubricator package will dramatically extend the life of the hydraulic pump and reduce downtime for only \$150.00.



Part number 2010 Regulator, Separator and Lubricator package comes complete with bracket, hardware, air fittings, and tubing. We will install it on a new unit at no charge if both are ordered at the same time. It can also be installed easily by the operator with the use of simple hand tools.

10600 Fallstone Rd Houston, TX 77099 Phone: 281-530-4848 or 1-800-627-9771